

| NO. | TYPE | REG | OPERATOR | ENGINE TYPE |
|-----|------------|--------|----------------------------|-----------------|
| 1 | B747-412F | 9V-SFI | SINGAPORE AIRLINES LIMITED | P&W PW4056 |
| 2 | B747-412F | 9V-SFK | SINGAPORE AIRLINES LIMITED | P&W PW4056 |
| 3 | B747-412F | 9V-SFM | SINGAPORE AIRLINES LIMITED | P&W PW4056 |
| 4 | B747-412F | 9V-SFN | SINGAPORE AIRLINES LIMITED | P&W PW4056 |
| 5 | B747-412F | 9V-SFO | SINGAPORE AIRLINES LIMITED | P&W PW4056 |
| 6 | B747-412F | 9V-SFP | SINGAPORE AIRLINES LIMITED | P&W PW4056 |
| 7 | B747-412F | 9V-SFQ | SINGAPORE AIRLINES LIMITED | P&W PW4056 |
| 8 | B777-312 | 9V-SYF | SINGAPORE AIRLINES LIMITED | RB211-TRENT 892 |
| 9 | B777-312 | 9V-SYH | SINGAPORE AIRLINES LIMITED | RB211-TRENT 892 |
| 10 | B777-312 | 9V-SYI | SINGAPORE AIRLINES LIMITED | RB211-TRENT 892 |
| 11 | B777-312 | 9V-SYJ | SINGAPORE AIRLINES LIMITED | RB211-TRENT 892 |
| 12 | B777-312 | 9V-SYL | SINGAPORE AIRLINES LIMITED | RB211-TRENT 892 |
| 13 | B777-312ER | 9V-SWA | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 14 | B777-312ER | 9V-SWB | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 15 | B777-312ER | 9V-SWD | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 16 | B777-312ER | 9V-SWE | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 17 | B777-312ER | 9V-SWF | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 18 | B777-312ER | 9V-SWG | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 19 | B777-312ER | 9V-SWH | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 20 | B777-312ER | 9V-SWI | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 21 | B777-312ER | 9V-SWJ | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 22 | B777-312ER | 9V-SWK | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 23 | B777-312ER | 9V-SWL | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 24 | B777-312ER | 9V-SWM | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 25 | B777-312ER | 9V-SWN | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 26 | B777-312ER | 9V-SWO | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 27 | B777-312ER | 9V-SWP | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 28 | B777-312ER | 9V-SWQ | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 29 | B777-312ER | 9V-SWR | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 30 | B777-312ER | 9V-SWS | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 31 | B777-312ER | 9V-SWT | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 32 | B777-312ER | 9V-SWU | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 33 | B777-312ER | 9V-SWV | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 34 | B777-312ER | 9V-SWW | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 35 | B777-312ER | 9V-SWY | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 36 | B777-312ER | 9V-SWZ | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 37 | B777-312ER | 9V-SNA | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 38 | B777-312ER | 9V-SNB | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 39 | B777-312ER | 9V-SNC | SINGAPORE AIRLINES LIMITED | GE90-115B |
| 40 | B777-212ER | 9V-SVB | SINGAPORE AIRLINES LIMITED | RB211-TRENT 892 |
| 41 | B777-212ER | 9V-SVC | SINGAPORE AIRLINES LIMITED | RB211-TRENT 892 |
| 42 | B777-212ER | 9V-SVE | SINGAPORE AIRLINES LIMITED | RB211-TRENT 892 |
| 43 | B777-212ER | 9V-SVM | SINGAPORE AIRLINES LIMITED | RB211-TRENT 892 |
| 44 | B777-212ER | 9V-SVN | SINGAPORE AIRLINES LIMITED | RB211-TRENT 892 |
| 45 | B777-212 | 9V-SRM | SINGAPORE AIRLINES LIMITED | RB211-TRENT 884 |
| 46 | B777-212 | 9V-SQJ | SINGAPORE AIRLINES LIMITED | RB211-TRENT 884 |
| 47 | B777-212 | 9V-SQL | SINGAPORE AIRLINES LIMITED | RB211-TRENT 884 |
| 48 | B777-212 | 9V-SQM | SINGAPORE AIRLINES LIMITED | RB211-TRENT 884 |
| 49 | B777-212 | 9V-SQN | SINGAPORE AIRLINES LIMITED | RB211-TRENT 884 |
| 50 | B787-10 | 9V-SCA | SINGAPORE AIRLINES LIMITED | TRENT 1000-J3 |
| 51 | B787-10 | 9V-SCB | SINGAPORE AIRLINES LIMITED | TRENT 1000-J3 |
| 52 | B787-10 | 9V-SCC | SINGAPORE AIRLINES LIMITED | TRENT 1000-J3 |
| 53 | B787-10 | 9V-SCD | SINGAPORE AIRLINES LIMITED | TRENT 1000-J3 |
| 54 | B787-10 | 9V-SCE | SINGAPORE AIRLINES LIMITED | TRENT 1000-J3 |

| NO. | TYPE | REG | OPERATOR | ENGINE TYPE |
|-----|----------|--------|----------------------------|------------------|
| 55 | B787-10 | 9V-SCF | SINGAPORE AIRLINES LIMITED | TRENT 1000-J3 |
| 56 | B787-10 | 9V-SCG | SINGAPORE AIRLINES LIMITED | TRENT 1000-J3 |
| 57 | B787-10 | 9V-SCH | SINGAPORE AIRLINES LIMITED | TRENT 1000-J3 |
| 58 | B787-10 | 9V-SCI | SINGAPORE AIRLINES LIMITED | TRENT 1000-J3 |
| 59 | B787-10 | 9V-SCJ | SINGAPORE AIRLINES LIMITED | TRENT 1000-J3 |
| 60 | B787-10 | 9V-SCK | SINGAPORE AIRLINES LIMITED | TRENT 1000-J3 |
| 61 | B787-10 | 9V-SCL | SINGAPORE AIRLINES LIMITED | TRENT 1000-J3 |
| 62 | B787-10 | 9V-SCM | SINGAPORE AIRLINES LIMITED | TRENT 1000-J3 |
| 63 | B787-10 | 9V-SCN | SINGAPORE AIRLINES LIMITED | TRENT 1000-J3 |
| 64 | A330-343 | 9V-STC | SINGAPORE AIRLINES LIMITED | RB211-TRENT 772B |
| 65 | A330-343 | 9V-STQ | SINGAPORE AIRLINES LIMITED | RB211-TRENT 772B |
| 66 | A330-343 | 9V-STU | SINGAPORE AIRLINES LIMITED | RB211-TRENT 772B |
| 67 | A330-343 | 9V-STZ | SINGAPORE AIRLINES LIMITED | RB211-TRENT 772B |
| 68 | A330-343 | 9V-SSA | SINGAPORE AIRLINES LIMITED | RB211-TRENT 772B |
| 69 | A330-343 | 9V-SSB | SINGAPORE AIRLINES LIMITED | RB211-TRENT 772B |
| 70 | A330-343 | 9V-SSC | SINGAPORE AIRLINES LIMITED | RB211-TRENT 772B |
| 71 | A330-343 | 9V-SSD | SINGAPORE AIRLINES LIMITED | RB211-TRENT 772B |
| 72 | A330-343 | 9V-SSE | SINGAPORE AIRLINES LIMITED | RB211-TRENT 772B |
| 73 | A330-343 | 9V-SSF | SINGAPORE AIRLINES LIMITED | RB211-TRENT 772B |
| 74 | A330-343 | 9V-SSG | SINGAPORE AIRLINES LIMITED | RB211-TRENT 772B |
| 75 | A330-343 | 9V-SSH | SINGAPORE AIRLINES LIMITED | RB211-TRENT 772B |
| 76 | A330-343 | 9V-SSI | SINGAPORE AIRLINES LIMITED | RB211-TRENT 772B |
| 77 | A350-941 | 9V-SMA | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 78 | A350-941 | 9V-SMB | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 79 | A350-941 | 9V-SMC | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 80 | A350-941 | 9V-SMD | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 81 | A350-941 | 9V-SME | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 82 | A350-941 | 9V-SMF | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 83 | A350-941 | 9V-SMG | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 84 | A350-941 | 9V-SMH | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 85 | A350-941 | 9V-SMI | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 86 | A350-941 | 9V-SMJ | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 87 | A350-941 | 9V-SMK | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 88 | A350-941 | 9V-SML | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 89 | A350-941 | 9V-SMM | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 90 | A350-941 | 9V-SMN | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 91 | A350-941 | 9V-SMO | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 92 | A350-941 | 9V-SMP | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 93 | A350-941 | 9V-SMQ | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 94 | A350-941 | 9V-SMR | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 95 | A350-941 | 9V-SMS | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 96 | A350-941 | 9V-SMT | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 97 | A350-941 | 9V-SMU | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 98 | A350-941 | 9V-SMV | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 99 | A350-941 | 9V-SMW | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 100 | A350-941 | 9V-SMY | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 101 | A350-941 | 9V-SMZ | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 102 | A350-941 | 9V-SGA | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 103 | A350-941 | 9V-SGB | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 104 | A350-941 | 9V-SGC | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 105 | A350-941 | 9V-SGD | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 106 | A350-941 | 9V-SGE | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 107 | A350-941 | 9V-SGF | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 108 | A350-941 | 9V-SGG | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |

| NO. | TYPE | REG | OPERATOR | ENGINE TYPE |
|-----|----------|--------|----------------------------|-----------------|
| 109 | A350-941 | 9V-SHA | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 110 | A350-941 | 9V-SHB | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 111 | A350-941 | 9V-SHC | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 112 | A350-941 | 9V-SHD | SINGAPORE AIRLINES LIMITED | TRENT XWB-84 |
| 113 | A350-941 | 9V-SHE | SINGAPORE AIRLINES LIMITED | TRENT XWB-75 |
| 114 | A350-941 | 9V-SHF | SINGAPORE AIRLINES LIMITED | TRENT XWB-75 |
| 115 | A350-941 | 9V-SHG | SINGAPORE AIRLINES LIMITED | TRENT XWB-75 |
| 116 | A350-941 | 9V-SHH | SINGAPORE AIRLINES LIMITED | TRENT XWB-75 |
| 117 | A350-941 | 9V-SHI | SINGAPORE AIRLINES LIMITED | TRENT XWB-75 |
| 118 | A350-941 | 9V-SHJ | SINGAPORE AIRLINES LIMITED | TRENT XWB-75 |
| 119 | A380-841 | 9V-SKF | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 120 | A380-841 | 9V-SKG | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 121 | A380-841 | 9V-SKH | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 122 | A380-841 | 9V-SKI | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 123 | A380-841 | 9V-SKJ | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 124 | A380-841 | 9V-SKK | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 125 | A380-841 | 9V-SKL | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 126 | A380-841 | 9V-SKM | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 127 | A380-841 | 9V-SKN | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 128 | A380-841 | 9V-SKP | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 129 | A380-841 | 9V-SKQ | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 130 | A380-841 | 9V-SKR | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 131 | A380-841 | 9V-SKS | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 132 | A380-841 | 9V-SKT | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 133 | A380-841 | 9V-SKU | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 134 | A380-841 | 9V-SKV | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 135 | A380-841 | 9V-SKW | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 136 | A380-841 | 9V-SKY | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 137 | A380-841 | 9V-SKZ | SINGAPORE AIRLINES LIMITED | RB211-TRENT 970 |
| 138 | A320-232 | 9V-TAN | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 139 | A320-232 | 9V-TAO | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 140 | A320-232 | 9V-TAQ | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 141 | A320-232 | 9V-TAU | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 142 | A320-232 | 9V-TAV | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 143 | A320-232 | 9V-TAX | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 144 | A320-232 | 9V-TAZ | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 145 | A319-132 | 9V-TRC | SCOOT TIGERAIR PTE LTD | IAE V2524-A5 |
| 146 | A320-232 | 9V-TRD | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 147 | A320-232 | 9V-TRE | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 148 | A320-232 | 9V-TRH | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 149 | A320-232 | 9V-TRI | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 150 | A320-232 | 9V-TRK | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 151 | A320-232 | 9V-TRL | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 152 | A320-232 | 9V-TRM | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 153 | A320-232 | 9V-TRN | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 154 | A320-232 | 9V-TRO | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 155 | A320-232 | 9V-TRP | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 156 | A320-232 | 9V-TRQ | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 157 | A320-232 | 9V-TRR | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 158 | A320-232 | 9V-TRS | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 159 | A320-232 | 9V-TRT | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 160 | A320-232 | 9V-TRU | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 161 | A320-232 | 9V-TRV | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 162 | A320-232 | 9V-TRW | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |

| NO. | TYPE | REG | OPERATOR | ENGINE TYPE |
|-----|-----------|--------|------------------------|---------------|
| 163 | A320-232 | 9V-TRX | SCOOT TIGERAIR PTE LTD | IAE V2527-A5 |
| 164 | A320-271N | 9V-TNA | SCOOT TIGERAIR PTE LTD | PW1127G-JM |
| 165 | A320-271N | 9V-TNB | SCOOT TIGERAIR PTE LTD | PW1127G-JM |
| 166 | B787-8 | 9V-OFA | SCOOT TIGERAIR PTE LTD | TRENT 1000-G2 |
| 167 | B787-8 | 9V-OFB | SCOOT TIGERAIR PTE LTD | TRENT 1000-G2 |
| 168 | B787-8 | 9V-OFD | SCOOT TIGERAIR PTE LTD | TRENT 1000-G2 |
| 169 | B787-8 | 9V-OFD | SCOOT TIGERAIR PTE LTD | TRENT 1000-G2 |
| 170 | B787-8 | 9V-OFE | SCOOT TIGERAIR PTE LTD | TRENT 1000-G2 |
| 171 | B787-8 | 9V-OFG | SCOOT TIGERAIR PTE LTD | TRENT 1000-G2 |
| 172 | B787-8 | 9V-OFH | SCOOT TIGERAIR PTE LTD | TRENT 1000-G2 |
| 173 | B787-8 | 9V-OFI | SCOOT TIGERAIR PTE LTD | TRENT 1000-G2 |
| 174 | B787-8 | 9V-OFJ | SCOOT TIGERAIR PTE LTD | TRENT 1000-G2 |
| 175 | B787-8 | 9V-OFK | SCOOT TIGERAIR PTE LTD | TRENT 1000-G3 |
| 176 | B787-9 | 9V-OJA | SCOOT TIGERAIR PTE LTD | TRENT 1000-J2 |
| 177 | B787-9 | 9V-OJB | SCOOT TIGERAIR PTE LTD | TRENT 1000-J2 |
| 178 | B787-9 | 9V-OJC | SCOOT TIGERAIR PTE LTD | TRENT 1000-J2 |
| 179 | B787-9 | 9V-OJD | SCOOT TIGERAIR PTE LTD | TRENT 1000-J2 |
| 180 | B787-9 | 9V-OJE | SCOOT TIGERAIR PTE LTD | TRENT 1000-J2 |
| 181 | B787-9 | 9V-OJF | SCOOT TIGERAIR PTE LTD | TRENT 1000-J2 |
| 182 | B787-9 | 9V-OJG | SCOOT TIGERAIR PTE LTD | TRENT 1000-J3 |
| 183 | B787-9 | 9V-OJH | SCOOT TIGERAIR PTE LTD | TRENT 1000-J3 |
| 184 | B787-9 | 9V-OJI | SCOOT TIGERAIR PTE LTD | TRENT 1000-J3 |
| 185 | B787-9 | 9V-OJJ | SCOOT TIGERAIR PTE LTD | TRENT 1000-J3 |
| 186 | B737-800 | 9V-MGA | SILKAIR (S) PTE LTD | CFM56-7B27 |
| 187 | B737-800 | 9V-MGB | SILKAIR (S) PTE LTD | CFM56-7B27 |
| 188 | B737-800 | 9V-MGC | SILKAIR (S) PTE LTD | CFM56-7B27 |
| 189 | B737-800 | 9V-MGD | SILKAIR (S) PTE LTD | CFM56-7B27 |
| 190 | B737-800 | 9V-MGE | SILKAIR (S) PTE LTD | CFM56-7B27 |
| 191 | B737-800 | 9V-MGF | SILKAIR (S) PTE LTD | CFM56-7B27 |
| 192 | B737-800 | 9V-MGG | SILKAIR (S) PTE LTD | CFM56-7B27 |
| 193 | B737-800 | 9V-MGH | SILKAIR (S) PTE LTD | CFM56-7B27 |
| 194 | B737-800 | 9V-MGI | SILKAIR (S) PTE LTD | CFM56-7B27 |
| 195 | B737-800 | 9V-MGJ | SILKAIR (S) PTE LTD | CFM56-7B27 |
| 196 | B737-800 | 9V-MGK | SILKAIR (S) PTE LTD | CFM56-7B27 |
| 197 | B737-800 | 9V-MGL | SILKAIR (S) PTE LTD | CFM56-7B27 |
| 198 | B737-800 | 9V-MGM | SILKAIR (S) PTE LTD | CFM56-7B27 |
| 199 | B737-800 | 9V-MGN | SILKAIR (S) PTE LTD | CFM56-7B27 |
| 200 | B737-800 | 9V-MGO | SILKAIR (S) PTE LTD | CFM56-7B27 |
| 201 | B737-800 | 9V-MGP | SILKAIR (S) PTE LTD | CFM56-7B27 |
| 202 | B737-800 | 9V-MGQ | SILKAIR (S) PTE LTD | CFM56-7B27 |
| 203 | B737-8 | 9V-MBA | SILKAIR (S) PTE LTD | CFM LEAP-1B27 |
| 204 | B737-8 | 9V-MBB | SILKAIR (S) PTE LTD | CFM LEAP-1B27 |
| 205 | B737-8 | 9V-MBC | SILKAIR (S) PTE LTD | CFM LEAP-1B27 |
| 206 | B737-8 | 9V-MBD | SILKAIR (S) PTE LTD | CFM LEAP-1B27 |
| 207 | B737-8 | 9V-MBE | SILKAIR (S) PTE LTD | CFM LEAP-1B27 |
| 208 | B737-8 | 9V-MBF | SILKAIR (S) PTE LTD | CFM LEAP-1B27 |
| 209 | A320-233 | 9V-SLL | SILKAIR (S) PTE LTD | IAE V2527-A5 |
| 210 | A320-233 | 9V-SLM | SILKAIR (S) PTE LTD | IAE V2527-A5 |
| 211 | A320-233 | 9V-SLO | SILKAIR (S) PTE LTD | IAE V2527-A5 |
| 212 | A320-233 | 9V-SLP | SILKAIR (S) PTE LTD | IAE V2527-A5 |
| 213 | A320-233 | 9V-SLQ | SILKAIR (S) PTE LTD | IAE V2527-A5 |
| 214 | A320-233 | 9V-SLR | SILKAIR (S) PTE LTD | IAE V2527-A5 |
| 215 | A320-233 | 9V-SLS | SILKAIR (S) PTE LTD | IAE V2527-A5 |
| 216 | A319-133 | 9V-SBG | SILKAIR (S) PTE LTD | IAE V2527M-A5 |

| NO. | TYPE | REG | OPERATOR | ENGINE TYPE |
|-----|-------------|--------|-----------------------------------|---------------------|
| 217 | A319-133 | 9V-SBH | SILKAIR (S) PTE LTD | IAE V2527M-A5 |
| 218 | A320-232 | 9V-JSA | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 219 | A320-232 | 9V-JSB | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 220 | A320-232 | 9V-JSF | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 221 | A320-232 | 9V-JSH | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 222 | A320-232 | 9V-JSI | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 223 | A320-232 | 9V-JSJ | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 224 | A320-232 | 9V-JSK | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 225 | A320-232 | 9V-JSL | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 226 | A320-232 | 9V-JSM | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 227 | A320-232 | 9V-JSN | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 228 | A320-232 | 9V-JSO | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 229 | A320-232 | 9V-JSP | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 230 | A320-232 | 9V-JSQ | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 231 | A320-232 | 9V-JSR | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 232 | A320-232 | 9V-JSS | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 233 | A320-232 | 9V-JSU | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 234 | A320-232 | 9V-JSV | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 235 | A320-232 | 9V-JSW | JETSTAR ASIA AIRWAYS PTE LTD | IAE V2527-A5 |
| 236 | DA40 | 9V-YFC | SINGAPORE YOUTH FLYING CLUB | LYCOMING IO-360-MIA |
| 237 | DA40 | 9V-YFD | SINGAPORE YOUTH FLYING CLUB | LYCOMING IO-360-MIA |
| 238 | DA40 | 9V-YFE | SINGAPORE YOUTH FLYING CLUB | LYCOMING IO-360-MIA |
| 239 | DA40 | 9V-YFF | SINGAPORE YOUTH FLYING CLUB | LYCOMING IO-360-MIA |
| 240 | DA40 | 9V-YFG | SINGAPORE YOUTH FLYING CLUB | LYCOMING IO-360-MIA |
| 241 | DA40 | 9V-YFH | SINGAPORE YOUTH FLYING CLUB | LYCOMING IO-360-MIA |
| 242 | DA40 | 9V-YFI | SINGAPORE YOUTH FLYING CLUB | LYCOMING IO-360-MIA |
| 243 | DA40 | 9V-YFJ | SINGAPORE YOUTH FLYING CLUB | LYCOMING IO-360-MIA |
| 244 | DA40 | 9V-YFK | SINGAPORE YOUTH FLYING CLUB | LYCOMING IO-360-MIA |
| 245 | DA40 | 9V-YFL | SINGAPORE YOUTH FLYING CLUB | LYCOMING IO-360-MIA |
| 246 | DA40 | 9V-YFM | SINGAPORE YOUTH FLYING CLUB | LYCOMING IO-360-MIA |
| 247 | DA40 | 9V-YFN | SINGAPORE YOUTH FLYING CLUB | LYCOMING IO-360-MIA |
| 248 | DA40 | 9V-YFO | SINGAPORE YOUTH FLYING CLUB | LYCOMING IO-360-MIA |
| 249 | SOCATA TB9C | 9V-BOZ | REPUBLIC OF SINGAPORE FLYING CLUB | LYCOMING 0-320-D2a |
| 250 | CESSNA 172N | 9V-BOQ | SELETAR FLYING CLUB | LYCOMING 0-320-H |
| 251 | EC120B | 9V-RWF | ST AEROSPACE ENGINEERING PTE LTD | TURBOMECA ARRIUS 2F |